


Shock pulse transducer with quick connector



TRA-30 is a shock pulse transducer with quick connector. It is used for measurements on permanently installed adapters. The quick connector forms a bayonet connection together with the adapter.

To attach the TRA-30 to an adapter, push the transducer firmly onto the adapter and twist it clockwise.

Twist counter clockwise to unfasten the transducer.

Technical data

| | |
|-------------------|-------------------|
| Measuring range | Max. 100 dBsv |
| Design | Sealed |
| Temperature range | -30° to +70° C |
| Material, spanner | Blacknited steel |
| Handle cover | Urethan |
| Coaxial cable | PVC, length 1.5 m |
| Connector | TNC |
| Weight | 250 g |

Part numbers

| | |
|--------|----------------------------------------------|
| TRA-30 | Transducer with quick connector, incl. cable |
| CAB-30 | Cable for TRA-30 |

